

**TO BE FILLED BY THE INSPECTING OFFICER  
(Assistant Engineer/ Assistant Executive Engineer)**

Name of School : MES CENTRAL SCHOOL, KOZHIKODE

1. Name of the Officer : SOORYA V-B-
2. Location : Building No: 13/325 & 13/326 in RsnO 59/2A, 59/2C  
46/1A, 62/1, 62/4 Ward 13, Elatun, Kozhikode.
3. Period for which the certificate is issued: one year.
4. Types of building : RCC framed structure with GF, FF and second floor
5. Nature of defect if any :

- a) Foundation and basement : - NIL
- b) Superstructure: - NIL
- c) Doors and Windows : - NIL
- d) Wood work wrought and put up: - NIL
- e) Roof: - NIL
- f) Flooring: - NIL
- g) Miscellaneous(Cracks if any): NIL

6. Any major defects noticed which will  
render the building unsafe in any manner: No

7. Whether maintenance work have been done properly: Yes

8. Whether the Structure is sound or not for conducting classes: Yes

Note : 1. The stability of the structure should be examined also with  
reference to location altitude intensity of wind exposure to flood etc.

2. Any additional observation deemed necessary for the certificate,  
may be furnished separately with the certificate.

Certified that the school was inspected by me on 27/03/2023 and found to be  
fit/~~unfit~~ to conduct classes for the period for the reasons stated above.  
under normal wind and weather conditions

Place : Kozhikode

Date: 27/03/2023

Signature:

Designation:



**SOORYA V.B.**  
Assistant Engineer  
PWD Building Section No: 1  
Kozhikode